



WALKER
MANUFACTURING CO.

5925 EAST HARMONY ROAD
FORT COLLINS, CO 80528
(970) 221-5614
WALKERMOWERS.COM

ADVISORY BULLETIN #20272A

JULY 16, 2020
Revision A Dated July 23, 2020

SUBJECT: MB Transmission Change

MODELS AFFECTED: All MB tractors, S/N 14-126804 to 20-164922

|A

PURPOSE: Hydro-Gear modified the ZT3100 transmission housing used in the MB tractor. The new transmissions are slightly larger causing the RH transmission to not fit in the chassis without modification.

- The LH transmission does not require modifications.
- The RH transmission will require modification to the chassis and installation of a replacement mount for the idler arm spring. The necessary hardware and grind template are included with the Hydro Spring Tab Kit (P/N 4026-33).

PARTS REQUIRED:

1. 4026-35 Hydro-Gear ZT3100/RH (replacing 4026-11)
2. 4026-33 Hydro Spring Tab Kit

WARRANTY COVERAGE:

For transmission replacement under warranty, the additional one-time labor allowance for the Hydro Spring Tab Kit is 0.5 hour.



walkermowers.com